



Products: VC520 Pro2 / Expansion Speakerphone

VC520 Pro2 Firmware Version: 0.0.7204.14

VC520 Pro expansion speakerphone: v0.0.8000.10

Published Date: November 11, 2022

Copyright © 2022

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	1
Important Notice	3
New Features	3
Problems Fixed	5
Known Issues	6



Revision History and System Requirement

Firmware Version	Region	Date	Model
0.0.7204.14	WW	November 11, 2022	VC520 Pro2
0.0.7204.06	WW	June 17, 2022	VC520 Pro2
0.0.7204.04	WW	May 5, 2022	VC520 Pro2
0.0.7200.92	WW	December 1, 2021	VC520 Pro2
0.0.7200.80	WW	July 26, 2021	VC520 Pro2
0.0.7200.78	WW	July 8, 2021	VC520 Pro2
0.0.7200.64	WW	March 23, 2021	VC520 Pro2
0.0.8000.10	WW	June 11, 2020	VC520Pro expansion speakerphone





Important Notice

VC520 Pro2

1. PTZApp2 should be upgraded to v. 2.0.1030.32 (MAC); v. 2.0.1044.48 (Windows) to get full functions.
2. The smart frame detection distance is up to 7~10 meters. If more than 10 meters, the accuracy may drop.
3. H.264 IP video streaming supports Windows 7 &10. (not supports Windows 8.1)
4. During system upgrade, please DON'T turn off the power for any reasons.

Expansion speakerphone

1. Requirements VC520 Pro2 Firmware version: v7200.64 or later
2. The expansion speakerphone cannot be the main speakerphone; it can only be used with the VC520 Pro2.
3. The VC520 Pro2 can support up to two expansion speakerphones, however, the daisy-chain expansion cable cannot exceed over 40m in total.
4. Please connect the power supply for the expansion speakerphone when daisy-chaining over 20m.
5. Please connect the power supply when upgrading the firmware for the expansion speakerphone.
6. The speakerphone cables and power adapter will be included in the package contents.




New Features

VC520 Pro2

Firmware Version	New Features
0.0.7204.14	- Add VISCA command: - Mute, Volume - Inquiring Tracking Status - Get People Counting Information via VISCA over IP - New Model Support for Preset Link (IP Mode) - Yamaha RM-CR, RM-CG, RM-TT - Removed default password of RTSP for privacy - Will Change Tracking Mode to “Manual Frame” once user manually set PTZ
0.0.7204.06	- Support Smart Gallery feature (*it requires PTZApp2 running in computer) - Improved Preset feature
0.0.7204.04	- Support big data - Add VISCA command: Power-Reset; Power_On/Off, Preset framing tracking - Improve remote control sensitivity - Improve auto frame accuracy performance - Support hostname editing in IP web page - Support SSL on/off in PTZApp2 - Support Preset link via IP for audio tracking with Shure and Sennheiser Please use latest PTZApp2 to enable functions of #2, 6, 7.
0.0.7200.92	- Support setting preset point with manual focus adjustment. - Support H.265 RTSP - Support total zoom up to 24x - Support DHCP hostname information (default is camera model name) - Change load/set preset UX behavior in IP page and PTZApp2
0.0.7200.80	- Change framing size description: change “Loose” to “Wide” - Image default setting change
0.0.7200.78	Add “framing size” function. When auto framing, the zoom in size has different options so that the new comers can be detected for different using scenario. Please upgrade PTZApp2 to the latest version to have this function.



	 Tight (default): It provides a close-up view of meeting participants. Medium: It provides Establishes a medium view of meeting participants. Loose: It provides a wide view of meeting participants. - Change people count behavior. When streaming is off, people counting function keeps running so that 3rd party app still can get the data. - When under auto frame mode, whenever the USB streaming is on, camera will trigger framing detection for once no matter there is people or not. - Enhance Auto focus speed, especially when people are in front of whiteboard/ TV screen. - Enhance WDR performance.
0.0.7200.64	Improve sensitivity of Preset framing function and image clarity.

Expansion Speakerphone

Firmware Version	New Features
0.0.8000.10	Connected VC520 Pro2 firmware requirement: V.7200.64 or later

Problems Fixed

Firmware Version	Problem Fixed
0.0.7204.06	Enhanced memory allocation mechanism
0.0.7204.04	- Fix "load preset" position accuracy issue - Fix audio reboot issue when using VISCA command to reboot VC520 Pro2
0.0.7200.92	- Improve audio disconnection problem that may occur in some devices. - Fix the "lost focus issue" while loading a preset point which is set by manual focus method.
0.0.7200.80	- Fix Static IP issue - Fix video transform issue when 4:3 aspect ratio is selected
0.0.7200.78	Modify the audio speakerphone detection mechanism to fix the sound



	function may fail after using it for a period of time on certain computers*. * Please be noted that if your speakerphone doesn't connect status or no power after the system beginning power-on, it does not belong to this abnormal situation, please check your hardware device and the environment again.
0.0.7200.64	3. Fix bugs on framing proportion.

Known Issues

Firmware Version	
0.0.7204.04	None
0.0.7200.64	1. When RTSP and RTMP used at the same time, the camera video will be damaged and the sound will be incomplete. 2. RTSP uses 60fps and above 4M performance, the camera and sound will be abnormal. 3. The first use of RTSP after booting will require two operations.

