

Revision History:

---

Y/M/D	Author	DVR version	IP Cam Patch version
2014/8/25	Kelly	H8.03.02.00.16	2.5.106.13
2014/6/19	Kelly	H8.03.02.00.15	1.5.1014.3
2014/01/03	Kelly	H8.03.02.00.14j	1.5.1014.3
2013/09/06	Peter	H8.03.02.00.14e	1.1.100.6

Ps The latest update should be listed on the top



## Release Notes

---

Product	EH1004H-4 Nano, EH1008H-4 Nano
Version	H8.03.02.00.16
Introduction	Official release for New-version FW
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none"><li>1. Fix the bug of daylight-saving time misplay.</li><li>2. Update the IP Cam Patch to ver. 2.5.106.13.</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. Please install HDD first before running the system. User can only setup system setting if no HDD installed.</li><li>2. The frame rate of 2<sup>nd</sup> video stream of remote site is limited to 3fps per analog channel.</li><li>3. It would pop up a dialog to check compatibility with remote s/w installation in the first time in Windows 7 operating system.</li><li>4. Connection with 2 channel IP camera would be the optimized performance of hybrid application.</li><li>5. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.</li><li>6. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance.</li></ol>

## Others

Ps The latest update should be listed on the top



## Release Notes

---

Product	EH1004H-4 Nano, EH1008H-4 Nano
Version	H8.03.02.00.15
Introduction	Official release for New-version FW
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none"><li>1. Add ECC function.</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. Please install HDD first before running the system. User can only setup system setting if no HDD installed.</li><li>2. The frame rate of 2<sup>nd</sup> video stream of remote site is limited to 3fps per analog channel.</li><li>3. It would pop up a dialog to check compatibility with remote s/w installation in the first time in Windows 7 operating system.</li><li>4. Connection with 2 channel IP camera would be the optimized performance of hybrid application.</li><li>5. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.</li><li>6. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance.</li></ol>

## Others

Ps The latest update should be listed on the top



## Release Notes

---

Product	EH1004H-4 Nano, EH1008H-4 Nano
Version	H8.03.02.00.14j
Introduction	Official release for new IP Cam Patch 1.5.1014.3
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none"><li>1. Renew IP Cam Patch to ver. 1.5.1014.3</li><li>2. Resolve the bug that CM3000 failed to search alarm name from NANO.</li><li>3. Resolve the bug that the 4<sup>th</sup> channel of NANO doesn't react on the remote control under Playback mode.</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. Please install HDD first before running the system. User can only setup system setting if no HDD installed.</li><li>2. The frame rate of 2<sup>nd</sup> video stream of remote site is limited to 3fps per analog channel.</li><li>3. It would pop up a dialog to check compatibility with remote s/w installation at the first time in Windows 7 operating system.</li><li>4. Connection with 2 channel IP camera would be the optimized performance of hybrid application.</li><li>5. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.</li><li>6. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance.</li></ol>

## Others

Ps The latest update should be listed on the top



## Release Notes

---

Product	EH1004H-4 Nano, EH1008H-4 Nano
Version	H8.03.02.00.14e
Introduction	Official release for H.S.I implementation
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none"><li>1. Implement H.S.I module (High speed integration).</li><li>2. Solve bugs about camera setting could not be saved.</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. Please install HDD first before running the system. User can only setup system setting if no HDD installed.</li><li>2. The frame rate of 2<sup>nd</sup> video stream of remote site is limited to 3fps per analog channel.</li><li>3. It would pop up a dialog to check compatibility with remote s/w installation at the first time in Windows 7 operating system.</li><li>4. Connection with 2 channel IP camera would be the optimized performance of hybrid application.</li><li>5. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.</li><li>6. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance.</li></ol>

## Others

Ps The latest update should be listed on the top

