

Revision History:

---

Y/M/D	Author	NVR version	IP Cam Patch version
2015/09/11	Vivian	1.1.100.31	2.7.1027.29
2015/3/31	Chris	1.1.100.23	2.7.1019.21
2014/12/22	Chris	1.1.100.20	2.5.1014.15
2014/10/27	Chris	1.1.100.19	2.5.1014.15

Ps The latest update should be listed on the top



## Release Notes

---

Product	P5036-R, P5036-16-R
Version	1.1.100.31
Introduction	Fourth Official release
Hardware Compatibility	P5036-R, P5036-16-R
Operating Systems	N/A
Compatibility List	N/A
Change Log	<ol style="list-style-type: none"><li>1. Integrate CEB and Stationmaster POS protocol</li><li>2. Add POS baud rate 2400 and 4800</li><li>3. POS overlay implement</li><li>4. Improve HDD power reset problem (New Hardware).</li><li>5. Support System controller.</li><li>6. Upgrade IPCam patch to support AVer new IP Camera SD2026</li><li>7. Fix bug: HDD size over 12T causes playback catalog buffer out of range.</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. System will reboot automatically when remove the recording hard disk directly.</li><li>2. POS keywords alarm not support special characters.</li><li>3. Not support audio codec AAC.</li></ol>
Others	NA



## Release Notes

---

Product	P5036-R, P5036-16-R
Version	1.1.100.23
Introduction	Second Official release
Hardware Compatibility	P5036-R, P5036-16-R
Operating Systems	N/A
Compatibility List	N/A
Change Log	<ol style="list-style-type: none"><li>1. Upgrade IPCam patch to support AVer new IP Camera FV2006-1, FV2026, FD2020-1, ED5000.</li><li>2. Increase new feature:<ol style="list-style-type: none"><li>(1) Support motion detect function with 3<sup>rd</sup>-party camera.</li><li>(2) Increase IVA recording function.</li><li>(3) E-Map support preview function.</li><li>(4) Support schedule backup to NAS.</li><li>(5) Support POS key word alarm function.</li><li>(6) NVR support IPCam setting by google Chrome in camera setting page.</li><li>(7) Increase POS erase setting.</li><li>(8) Integrate Epson POS protocol.</li><li>(9) Increase recording authorization (Sunny bank PCR).</li><li>(10) Integrate ACS access control (Russia PCR).</li></ol></li><li>3. Improvement:<ol style="list-style-type: none"><li>(1) Real time display video when drag progress bar in playback mode.</li><li>(2) Only reserve AVer protocol when searching AVer homemade camera.</li></ol></li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. POS information and system log will lose caused by the abnormal interruption of power supply when using RAID5.</li><li>2. System will reboot automatically when remove the recording hard</li></ol>



## Release Notes

---

Product P5036-R, P5036-16-R

disk directly.

3. PCViewer doesn't support auto re-connection in this version.
4. When connect to ED5000 with quad ceiling mode, display streaming won't match real channel, will fix in next version.
5. When setting camera by google Chrome in NVR, camera live view can't display on Chrome browser, this feature is only for quick setting.

Others NA



## Release Notes

---

Product	P5036-R, P5036-16-R
Version	1.1.100.20
Introduction	Second Official release
Hardware Compatibility	P5036-R, P5036-16-R
Operating Systems	N/A
Compatibility List	N/A
Change Log	<ol style="list-style-type: none"><li>1. Fixed bugs to improve system stability.</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. POS information and system log will lose caused by the abnormal interruption of power supply when using RAID5.</li><li>2. System will reboot automatically when remove the recording hard disk directly.</li><li>3. PCViewer doesn't support auto re-connection in this version.</li></ol>
Others	NA



## Release Notes

---

Product	P5036-R, P5036-16-R
Version	1.1.100.19
Introduction	First Official release
Hardware Compatibility	P5036-R, P5036-16-R
Operating Systems	N/A
Compatibility List	N/A
Change Log	<ol style="list-style-type: none"><li>1. Support total 36ch IP camera (analog camera up to 16ch).</li><li>2. Support TCP type POS protocol.</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. POS information and system log will lose caused by the abnormal interruption of power supply when using RAID5.</li><li>2. System will reboot automatically when remove the recording hard disk directly.</li><li>3. PCViewer doesn't support auto re-connection in this version.</li></ol>
Others	NA

Ps The latest update should be listed on the top

