

Products: FONE520

Firmware Version: 0.0.0004.42

Published Date: June 15th, 2017

Copyright © 2016



Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

| | |
|--|---|
| Revision History and System Requirement..... | 2 |
| Important Notice..... | 3 |
| New Features..... | 4 |
| Problems Fixed..... | 5 |
| Known Issues..... | 6 |



Revision History and System Requirement

| Firmware Version | Region | Date | Model |
|------------------|--------|---------------|---------|
| 0.0.0004.42 | WW | June 15, 2017 | FONE520 |



Important Notice

1. Downgrading firmware to any older version is prohibited.
2. During system upgrade, please DON'T turn off the power for any reasons.
3. If speakerphone connected improperly, please re-connected correctly and it will take 3 seconds to reset.
4. When the speakerphone was excessive movement or environmental change. Speakerphone needs about 5 seconds to relearn AEC function.



New Features

| Firmware Version | New Features |
|------------------|----------------------------|
| 0.0.0004.42 | FW 1 st release |



Problems Fixed

| Firmware Version | Problem Fixed |
|------------------|---------------|
| 0.0.0004.42 | None |



Known Issues

| Firmware Version | Problem Fixed |
|------------------|---------------|
| 0.0.0004.42 | None |

