

Software Version: 0.0.4002.62



Published Date: April 7th, 2023

Copyright © 2023

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	3
Upgrade Instructions.....	3
New Features	4
Problems Fixed	5
Known Issues.....	5



Revision History and System Requirement

Software Version	Region	Date	Model
0.0.4002.62	WW	April 07, 2023	VB342
0.0.4002.58	WW	December 28, 2021	VB342
0.0.4002.54	WW	January 21, 2020	VB342
0.0.4002.52	WW	September 09, 2019	VB342
0.0.4002.50	WW	January 31, 2019	VB342
0.0.4002.48	WW	November 26 ,2018	VB342
0.0.4002.36	WW	November 09 ,2018	VB342
0.0.4002.34	WW	OCT.-11 ,2018	VB342
0.0.4002.24	WW	sept.-05 ,2018	VB342
0.0.4002.18	WW	June 22nd ,2018	VB342



Important Notice

Please don't unplug power adapter and USB port while FW updating.

It's suggested to upgrade to PTZApp2 with latest version: 2.0.1015.17 (MAC); v. 2.0.1019.24 (Windows)



New Features

Software Version	New Features
0.0.4002.58	N/A
0.0.4002.54	This version just adds some paramters for testing program in factory side
0.0.4002.52	Add ZOOM ROOM XU control (preset function)
0.0.4002.48	<ol style="list-style-type: none"> 1. Support" auto power on/off" function 2. Support " Enable/disable device buttons" function 3. Support " Displaylink enable/disable function (While connecting to Chrome box, please select "OFF" on PTZapp) <p>To enable/disable those functions, please install PTZapp with version 1.3.1074.75(Win)/ 1.3.1059.60(MAC)</p>
0.0.4002.36	None
0.0.4002.34	VB342 can be controlled by CAM540 remote control
0.0.4002.24	2nd release
0.0.4002.18	1 st release



Problems Fixed

Software Version	Problem Fixed
0.0.4002.62	Fix Microsoft Teams (Desktop Version) compatibility issue after Teams 2023 update.
0.0.4002.58	<ol style="list-style-type: none"> Fixing the zoom control issue in Win10 20H2 Removing 60fps to solve ePTZ issue
0.0.4002.54	None
0.0.4002.52	None
0.0.4002.50	Improve random over exposition issue
0.0.4002.48	None
0.0.4002.36	Adjust mipi parameter to fix random video stream error issue
0.0.4002.34	Fixing system hanging issue while using Zoom Room
0.0.4002.24	PTZapp couldn't find "home position"
0.0.4002.18	None

Known Issues

Software Version	Known Issues
0.0.4002.58	None
0.0.4002.54	None
0.0.4002.52	None
0.0.4002.50	None
0.0.4002.48	None
0.0.4002.36	None
0.0.4002.34	None
0.0.4002.18	None

