



Products: VB130

Firmware Version: 0.0.7302.08

Published Date: May. 20, 2022

Copyright © 2016

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	3
New Features	4
Problems Fixed	6
Known Issues	7



Revision History and System Requirement

Firmware Version	Region	Date
0.0.7302.08	WW	May 20, 2022
0.0.7300.84	WW	Jan. 27, 2022
0.0.7300.80	WW	NOV.24, 2021
0.0.7300.78	WW	OCT. 29, 2021
0.0.7300.76	WW	OCT. 22, 2021
0.0.7300.70	WW	August 25, 2021
0.0.7300.68	WW	July 30, 2021
0.0.7300.66	WW	July 06, 2021
0.0.7300.58	WW	June 04, 2021
0.0.7300.50	WW	April 28, 2021






Important Notice

1. During system upgrade, please DON'T turn off the power for any reasons.
2. PTZApp2 must be upgraded to 2.0.1025.26 (MAC); v. 2.0.1037.38 (Windows)



New Features

Firmware Version	New Features
0.0.7302.08	<ul style="list-style-type: none"> When camera pan, tilt, zoom function is operated, AI function will be disabled automatically Optimize auto frame function White balance function: add AWB/ATW mode to cover wider color range. Please use IP webpage or the latest PTZApp2 to set it up.  <ul style="list-style-type: none"> Add video frame rate 30fps/60fps. Default is 30fps to have better image quality.  <ul style="list-style-type: none"> Add SSL on/off setting in PTZApp2  <ul style="list-style-type: none"> Update JQuery version to version 3.5 or higher version
0.0.7300.84	<ul style="list-style-type: none"> Improve lower resolution (360p) image performance Change auto frame maximum zoom-in ratio from 4x to 3x
0.0.7300.80	None
0.0.7300.78	<ul style="list-style-type: none"> Enhance auto framing sensitivity
0.0.7300.76	<ul style="list-style-type: none"> Support 5xzoom. Please use latest PTZApp2 to enable it. Support disabling resolution lower than 720p. Please use latest PTZApp2 to set it up. <p>Notes: The default is disabling lower resolution since FW v.76. If you are using Webex VC software, please enable lower resolution because Webex normally requires very low resolution, otherwise, you will encounter black screen issue.</p>



	<ul style="list-style-type: none"> ● Support H.265 video format on IP streaming.
0.0.7300.70	<ul style="list-style-type: none"> ● Enhanced Audio Fence function by filtering out noise such as baby crying and dog barking even when they are within the camera view. ● Support the function of disabling resolution lower than 720p (except 848x400 resolution).
0.0.7300.68	<ul style="list-style-type: none"> ● Improve 4:3 ratio image quality
0.0.7300.66	<ul style="list-style-type: none"> ● Enhance audio tracking sensitivity to quicken the response speed. ● Add audio tracking idle time setting. When there is no one speaking after certain idle time, the camera will go back to frame all participants. ● Improve preview image quality of 360p and 480p in Teams app. ● Enhanced WDR performance ● Change people count behavior. When streaming is off, people counting function keeps running so that 3rd party app still can get the data.
0.0.7300.58	<ul style="list-style-type: none"> ● Include ZOOM people count API so that users can view in-room attendee count in ZOOM app. ● Include ZOOM preset, auto frame API so that users can see Preset and Auto frame button on ZoomRoom Controller app. ● Keep people counting running even when USB streaming is off.
0.0.7300.50	<p>Improve auto framing sensitivity</p> <p>Add Teams people count API</p>



Problems Fixed

Firmware Version	Problem Fixed
0.0.7302.08	<ul style="list-style-type: none"> ● Fix remote control sensitivity issue ● Fix mute control issue in Cisco Webex Meetings
0.0.7300.84	N/A
0.0.7300.80	Fix the IQ loading flow to avoid loading low resolution image while rebooting device.
0.0.7300.78	N/A
0.0.7300.76	Fix bug on audio connection lost issue: memory leakage issue Notes: If using AVer BT dongle, please insert it into VB130 before power on the device. Otherwise, the BT dongle function won't be activated.
0.0.7300.70	Fix bug on Teams MTR audio/video connection lost issue
0.0.7300.68	N/A
0.0.7300.66	Fix the UVC control (ex: zoom in) issues in Windows 10
0.0.7300.58	Fix the bug of auto frame: When people are closer to camera (within 1meters), auto frame won't have any action. Fix the bug of power on issue: When we re-plug power of VB130, PC may randomly not recognize the device.
0.0.7300.50	Fix audio tracking issue: When image mirror enables, the audio tracking will go to opposite position.

Known Issues

Firmware Version	Problem Fixed
0.0.7302.08	None
0.0.7300.84	None
0.0.7300.80	None
0.0.7300.78	None
0.0.7300.76	None
0.0.7300.70	None
0.0.7300.68	None
0.0.7300.66	None
0.0.7300.64	None
0.0.7300.58	None
0.0.7300.50	None

