



Products: VB342 Pro

Firmware Version: 0.0.7802.06

Published Date: March 1, 2023

Copyright © 2023

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT. **Content**

Revision History and System Requirement	2
Important Notice	3
New Features	4
Problems Fixed.....	5
Known Issues.....	6



Revision History and System Requirement

Firmware Version	Region	Date
0.0.7802.06	WW	March 1, 2023
0.07800.62	WW	September 6, 2022
0.0.7800.56	WW	June 20, 2022
0.0.7800.52	WW	April 21, 2022
0.0.7800.48	WW	April 12, 2022



Important Notice

1. During system upgrade, please DON'T turn off the power for any reasons.
2. PTZApp2 must be upgraded to v. 2.0.1032.36 (MAC); v. 2.0.1051.53 (Windows) to support latest functions.



New Features

Firmware Version	New Features
0.0.7802.06	N/A
0.0.7800.62	● Support Flicker Decrease on IFP / Monitor function via running PTZApp2 in PC or Web page connection ● Improve True WDR function performance
0.0.7800.56	● Improve Smart Gallery performance
0.0.7800.52	● Support AI functions via VISCA Over IP, such as audio tracking ● Improve sensitive range while using remote control ● Improve Auto frame performance
0.0.7800.48	● Support Smart Gallery function via running PTZApp2 in PC ● Enlarge default audio volume ● Improve audio tracking performance



Problems Fixed

Firmware Version	Problem Fixed
0.0.7802.06	Fixed minor bugs
0.0.7800.56	Fixed VISCA command:Power_Reset, Power_On, Power_Off
0.0.7800.52	N/A
0.0.7800.48	N/A



Known Issues

Firmware Version	Problem Fixed
0.0.7800.48	After device powers on, it takes around 1 min to enable Web page connection and audio tracking function.

