Release Notes

Product

- MT100

Supported Camera

- PTC310/PTC310U/PTC310H/PTC310N/PTC310UN/PTC310HN: 0.0.0000.21 or later
- PTC330/PTC330N/PTC330U: 0.0.0000.21 or later
- PTC115/PTC500S/PTC115+/PTC500+: 0.0.1000.47 or later
- PTZ310/PTZ310N/PTZ330/PTZ330N: 0.0.0000.56 or later
- PTC330UV2/PTC320UNV2/PTC320UV2/PTC310UV2/PTC310HWV2: 0.1.0000.23 or later
- PTZ310U(N)V2/PTZ330U(N)V2/PTZ211/PTZ231: 0.0.0000.24 or later
- TR211/TR315(N)/TR335(N): 0.0.0000.24 or later
- DL30: 7.0.0022.28 or later
- TR535: 0.0.0000.18 or later
- CAM550/VC550 V0.0.8004.20/CAM570: 0.0.8102.48 or later
- CAM520Pro3/VC520Pro3: 0.0.9602.18 or later
- TR615: 0.0.0000.21 or later
- TR322 0.0.0000.06 or later
- DL10: 7.1.0049.51 or later
- U50+: 0.2.1008.10 or later
- U70i: 1.0.0002.09 or later
- M11-8MV: 6.0.0023.25 or later
- F17+: 5.8.0009.11 or later

Version	0.2.0000.94
Release Date	2026/9/30
New Features	• Support Profile Copy • Support AVer TR322
Improvements	• N/A
Bug Fixed	• N/A
Notes and Recommendations	• For optimal performance, it is not recommended to connect both the U50+ and U70i to the MT100 simultaneously. • When using RTMP or HLS streaming, an audio input must be connected along with the video source; otherwise, the stream will fail. The audio should be connected to USB IN 2 on the MT100, and it can come directly from the camera or from an additional UAC-compatible device.
Known Issues	• When connecting and streaming a camera to the MT100 via USB, HDMI, or IP, and simultaneously outputting via USB, HDMI, IP, or NDI—while also accessing the MT100 through its device webpage—the output frame rate may drop below 60 fps.

Version	0.2.0000.87
Release Date	2026/3/27
New Features	• No new features in this release. This update focuses on system stability and performance optimizations.
Improvements	• N/A
Bug Fixed	• Miscellaneous bug fixes and performance improvements.
Notes and Recommendations	• For optimal performance, it is not recommended to connect both the U50+ and U70i to the MT100 simultaneously. • When using RTMP or HLS streaming, an audio input must be connected along with the video source; otherwise, the stream will fail. The audio should be connected to USB IN 2 on the MT100, and it can come directly from the camera or from an additional UAC-compatible device.
Known Issues	• When connecting and streaming a camera to the MT100 via USB, HDMI, or IP, and simultaneously outputting via USB, HDMI, IP, or NDI—while also accessing the MT100 through its device webpage—the output frame rate may drop below 60 fps.

Version	0.1.0000.83
Release Date	2025/12/30
New Features	• Added support for RTSP authentication on Video Conferencing Cameras to enable configuration of RTSP username and password to enhance stream access control and security.
Improvements	• N/A
Bug Fixed	• Miscellaneous bug fixes and performance improvements.
Notes and Recommendations	• For optimal performance, it is not recommended to connect both the U50+ and U70i to the MT100 simultaneously. • When using RTMP or HLS streaming, an audio input must be connected along with the video source; otherwise, the stream will fail. The audio should be connected to USB IN 2 on the MT100, and it can come directly from the camera or from an additional UAC-compatible device.
Known Issues	• When connecting and streaming a camera to the MT100 via USB, HDMI, or IP, and simultaneously outputting via USB, HDMI, IP, or NDI—while also accessing the MT100 through its device webpage—the output frame rate may drop below 60 fps.

Version	0.1.0000.81
Release Date	2025/11/03
New Feature	N/A
Improvements	N/A
Bug Fixed	Miscellaneous bug fixes and performance improvements.
Notes and Recommendations	• For optimal performance, it is not recommended to connect both the U50+ and U70i to the MT100 simultaneously. • When using RTMP or HLS streaming, an audio input must be connected along with the video source; otherwise, the stream will fail. The audio should be connected to USB IN 2 on the MT100, and it can come directly from the camera or from an additional UAC-compatible device.
Known Issues	• When connecting and streaming a camera to the MT100 via USB, HDMI, or IP, and simultaneously outputting via USB, HDMI, IP, or NDI—while also accessing the MT100 through its device webpage—the output frame rate may drop below 60 fps.

Version	0.1.0000.63
Release Date	2025/7/14
New Feature	Initial release.
Improvements	Initial release.
Notes and Recommendations	• For optimal performance, it is not recommended to connect both the U50+ and U70i to the MT100 simultaneously. • When using RTMP or HLS streaming, an audio input must be connected along with the video source; otherwise, the stream will fail. The audio should be connected to USB IN 2 on the MT100, and it can come directly from the camera or from an additional UAC-compatible device.
Known Issues	• When connecting and streaming a camera to the MT100 via USB, HDMI, or IP, and simultaneously outputting via USB, HDMI, IP, or NDI—while also accessing the MT100 through its device webpage—the output frame rate may drop below 60 fps.