

Revision History:

Y/M/D	Author	xxx version	xxx version
2014/8/22	Erica	H9.03.24.00.07L	2.5.106.13
2014/01/24	Erica	H9.03.24.00.07j	1.5.1014.3
2013/09/06	Peter	H9.03.24.00.07d	1.1.100.3

Ps The latest update should be listed on the top



Release Notes

Product EH1116H-4 Nano

Version H9.03.24.00.07L

Introduction Official release

Hardware NA
Compatibility

Operating Systems NA

Compatibility List NA

Change Log 1. Updated new IP CAM patch version (2.5.106.13).

Known Issues

1. Please install HDD first before running and remote/ISP upgrading the system. User can only setup system setting if no HDD installed.
2. The frame rate of 2nd video stream of remote site is limited to 7.5fps per analog channel.
3. It would pop up a dialog to check compatibility with remote s/w installation in the first time in Windows 7 operating system.
4. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.
5. TV and spot output support analog channel only.
6. PC Viewer two-way audio only can be supported at port 9999.
7. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance

Others

Ps The latest update should be listed on the top



Release Notes

Product EH1116H-4 Nano

Version H9.03.24.00.07j

Introduction Official release

Hardware Compatibility NA

Operating Systems NA

Compatibility List NA

Change Log

1. Updated new IP CAM patch version

Known Issues

1. Please install HDD first before running and remote/ISP upgrading the system. User can only setup system setting if no HDD installed.
2. The frame rate of 2nd video stream of remote site is limited to 7.5fps per analog channel.
3. It would pop up a dialog to check compatibility with remote s/w installation in the first time in Windows 7 operating system.
4. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.
5. TV and spot output support analog channel only.
6. PC Viewer two-way audio only can be supported at port 9999.
7. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance

Others

Ps The latest update should be listed on the top



Release Notes

Product EH1116H-4 Nano

Version H9.03.24.00.07d

Introduction Official release for H.S.I implementation

Hardware Compatibility NA

Operating Systems NA

Compatibility List NA

Change Log

1. Implement H.S.I module(High speed integration)
2. Solve bugs about camera setting could not be saved
3. Modify EPSON POS 0x00 issue

Known Issues

1. Please install HDD first before running and remote/ISP upgrading the system. User can only setup system setting if no HDD installed.
2. The frame rate of 2nd video stream of remote site is limited to 7.5fps per analog channel.
3. It would pop up a dialog to check compatibility with remote s/w installation in the first time in Windows 7 operating system.
4. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.
5. TV and spot output support analog channel only.
6. PC Viewer two-way audio only can be supported at port 9999.
7. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance

Others

Ps The latest update should be listed on the top

