Revision History:

Y/M/D	Author	DVR version	IP Cam Patch version
2015/03/26	Jane	v7.9.0.0035c	2.7.1010.11
2014/06/20	Jane	v7.9.0.0035c	2.3.104.5
2014/04/02	Jane	v7.9.0.0035b	1.1.100.2
2013/09/06	Peter	v7.9.0.0034a	1.1.100.2

Ps The latest update should be listed on the top

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. “AVer” is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Release Notes

Product	IWH3216 series
Version	v7.9.0.0035c
Introduction	Official release
Hardware Compatibility	N/A
Operating Systems	N/A
Compatibility List	N/A
Change Log	1. Fixed touch panel fail issue. 2. Updated new IPCam Patch version(2.7.1010.11)
Known Issues	1. The C drive cannot be set to the recording path. 2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally. 3. HDD format is not allowed in system setting while DVR is recording 4. Up to total 42 mega pixel resolution for all IP camera channels could be installed 5. VGA2 resolution is fixed in 1280x1024 6. Some Icon and UI will abnormal if main UI default setting is based on “Electric Red” 7. KVM switch is not supported 8. Install HDD first before booting the system to assign virtual memory to HDD automatically. 9. It needs to connect to its own power supply while connecting to external RS232 device. 10. CPU performance will increase at least 20% while the resolution of system display is setup over 1440x900. 11. Power-off process will take about 1 minute, DO NOT unplug power before the power is cut-off while data is still saving into

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. “AVer” is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Product	IWH3216 series
	DOM but the screen is black. 12. Please use 7.7.0.65 or above version of iMatrix for the usage of audio function in iMatrix program. 13. If network connection can't work fine in specific network environment, please re-plug network cable to check first. 14. Please setup alarm TV-out setting in DVR site.
Others	N/A

Ps The latest update should be listed on the top

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. "AVer" is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Release Notes

Product	IWH3216 series
Version	v7.9.0.0035c
Introduction	Official release
Hardware Compatibility	N/A
Operating Systems	N/A
Compatibility List	N/A
Change Log	1. Updated new IP Cam Patch version
Known Issues	1. The C drive cannot be set to the recording path. 2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally. 3. HDD format is not allowed in system setting while DVR is recording 4. Up to total 42 mega pixel resolution for all IP camera channels could be installed 5. VGA2 resolution is fixed in 1280x1024 6. Some Icon and UI will abnormal if main UI default setting is based on “Electric Red” 7. KVM switch is not supported 8. Install HDD first before booting the system to assign virtual memory to HDD automatically. 9. It needs to connect to its own power supply while connecting to external RS232 device. 10. CPU performance will increase at least 20% while the resolution of system display is setup over 1440x900. 11. Power-off process will take about 1 minute, DO NOT unplug power before the power is cut-off while data is still saving into DOM but the screen is black.

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. “AVer” is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Release Notes

Product	IWH3216 series
	12. Please use 7.7.0.65 or above version of iMatrix for the usage of audio function in iMatrix program. 13. If network connection can't work fine in specific network environment, please re-plug network cable to check first. 14. Please setup alarm TV-out setting in DVR site.
Others	N/A

Ps The latest update should be listed on the top

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. "AVer" is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Release Notes

Product	IWH3216 series
Version	v7.9.0.0035b
Introduction	Patch release
Hardware Compatibility	N/A
Operating Systems	N/A
Compatibility List	N/A

Change Log

1. Fix problem about the files cannot import to system when user no installed the hard disk.
2. Fix the problem of abnormal motion detection operation.
3. Fix problem about server name changes of setup wizard.
4. Fix problem about the maximum connection of remote real time playback is up to 3.

Known Issues

1. The C drive cannot be set to the recording path.
2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally.
3. HDD format is not allowed in system setting while DVR is recording
4. Up to total 42 mega pixel resolution for all IP camera channels could be installed
5. VGA2 resolution is fixed in 1280x1024
6. Some Icon and UI will abnormal if main UI default setting is based on “Electric Red”
7. KVM switch is not supported
8. Install HDD first before booting the system to assign virtual memory to HDD automatically.
9. It needs to connect to its own power supply while connecting to external RS232 device.
10. CPU performance will increase at least 20% while the resolution of system display is setup over 1440x900.
11. Power-off process will take about 1 minute, DO NOT unplug power before the power is cut-off while data is still saving into DOM but the screen is black.

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. “AVer” is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Release Notes

Product	IWH3216 series
	12. Please use 7.7.0.65 or above version of iMatrix for the usage of audio function in iMatrix program. 13. If network connection can’t work fine in specific network environment, please re-plug network cable to check first. 14. Please setup alarm TV-out setting in DVR site.
Others	N/A

Ps The latest update should be listed on the top

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. “AVer” is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Release Notes

Product	IWH3216 series
Version	v7.9.0.0034a
Introduction	Official release for H.S.I implementation
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	1. Implement H.S.I module(High speed integration)
Known Issues	1. The C drive cannot be set to the recording path. 2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally. 3. HDD format is not allowed in system setting while DVR is recording 4. Up to total 42 mega pixel resolution for all IP camera channels could be installed 5. VGA2 resolution is fixed in 1280x1024 6. Some Icon and UI will abnormal if main UI default setting is based on "Electric Red" 7. KVM switch is not supported 8. Install HDD first before booting the system to assign virtual memory to HDD automatically. 9. It needs to connect to its own power supply while connecting to external RS232 device. 10. CPU performance will increase at least 20% while the resolution of system display is setup over 1440x900. 11. Power-off process will take about 1 minute, DO NOT unplug power before the power is cut-off while data is still saving into DOM but the screen is black. 12. Please use 7.7.0.65 or above version of iMatrix for the usage of audio function in

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. "AVer" is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.

Product	IWH3216 series

iMatrix program.

13. If network connection can't work fine in specific network environment, please re-plug network cable to check first.
14. Please setup alarm TV-out setting in DVR site

Others

Ps The latest update should be listed on the top

© 2013 AVer Information Inc. All rights reserved.
All rights of this object belong to AVer Information Inc. Reproduced or transmitted in any form or by any means without the prior written permission of AVer Information Inc. is prohibited. All information or specifications are subject to change without prior notice. "AVer" is a trademark owned by AVer Information Inc. Other trademarks used herein for description purpose only belong to each of their companies.