

AVer MT100S Firmware Release Notes – September 30th, 2026

VERSION	**0.2.0000.94**
CAMERA COMPATIBILITY	• PTC310/PTC310U/PTC310H/PTC310N/PTC310UN/PTC310HN: 0.0.0000.21 or later • PTC330/PTC330N/PTC330U: 0.0.0000.21 or later • PTC115/PTC500S/PTC115+/PTC500+: 0.0.1000.47 or later • PTZ310/PTZ310N/PTZ330/PTZ330N: 0.0.0000.56 or later • PTC330UV2/PTC320UNV2/PTC320UV2/PTC310UV2/PTC310HWV2: 0.1.0000.23 or later • PTZ310U(N)V2/PTZ330U(N)V2/PTZ211/PTZ231: 0.0.0000.24 or later • TR211/TR315(N)/TR335(N): 0.0.0000.24 or later • DL30: 7.0.0022.28 or later • TR535: 0.0.0000.18 or later • CAM550/VC550 V0.0.8004.20/CAM570: 0.0.8102.48 or later • CAM520Pro3/VC520Pro3: 0.0.9602.18 or later • TR615: 0.0.0000.21 or later • TR322 0.0.0000.06 or later • DL10: 7.1.0049.51 or later • U50+: 0.2.1008.10 or later • U70i: 1.0.0002.09 or later • M11-8MV: 6.0.0023.25 or later • F17+: 5.8.0009.11 or later
MICROPHONE COMPATIBILITY	• Audio Technica ■ ATND1061DAN, ATND1061LK ■ ATUC-50 ■ ATUC-IR ■ ESW - Engineered Sound Wireless - Dante

0.2.0000.94
 	
Release date:
 	
September 30, 2026
	New Features
	
	• Support camera Framing on MT
	  • Supports TRV3 v75 or later
	  • After selecting Framing on MT, suggest checking" Maintain Current FOV" on Camera webpage
	  • 
	
	
	
	• Support Multi-Mic

	• This “Multi-Mic” feature will analyze real-time audio feeds from ceiling microphones and dynamically determines channel priority based on the microphone's input volume levels, ensuring smooth and stable camera switching. • *Note:* Enabled by default with no option to disable. • Support Profile Copy • Support up to 256 gooseneck mic • Support AVer TR322 **Important Note on Voice Tracking Installation:** • For optimal performance, consider the environment, materials, and distances. Assess room size, layout, and acoustics. Different surfaces affect sound reflection and absorption. Maintain proper distances between devices and the coverage area. For the best results, consult a local AVer tech expert to address specific needs and troubleshoot potential issues. **Known Issues:** • When connecting and streaming a camera to the MT100S via USB, HDMI, or IP, and simultaneously output via USB, HDMI, IP, or NDI—while also accessing the MT100S through its device webpage—the output frame rate may drop below 60 fps. **Notes and Recommendations:** • For optimal performance, it is not recommended to connect both the U50+ and U70i to the MT100S simultaneously. • When using RTMP or HLS streaming, an audio input must be connected along with the video source; otherwise, the stream will fail. The audio should be connected to USB IN 2 on the MT100S, and it can come directly from the camera or from an additional UAC-compatible device. **Bug Fixed:** • N/A