

Revision History:

Y/M/D	Author	FW version	IP Cam Patch version
2014/9/2	Kelly	X9.03.24.00.07I	2.5.106.13
2013/9/6	Peter	X9.03.24.00.07j	1.1.100.3

Ps The latest update should be listed on the top



Release Notes

Product	EH6216H+, EH6108H+
Version	X9.03.24.00.071
Introduction	Official Release for New IP Cam Patch
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Fix the bug of daylight-saving time misplay.2. Update the IP Cam Patch to ver. 2.5.106.13
Known Issues	<ol style="list-style-type: none">1. Please install HDD first before running and remote/ISP upgrading the system. User can only setup system setting if no HDD installed.2. The frame rate of 2nd video stream of remote site is limited to 15fps per analog channel.3. It would pop up a dialog to check compatibility with remote s/w installation in the first time in Windows 7 operating system.4. Connection with 8 channel IP camera would be the optimized performance of hybrid application. Please use Intelligent streaming to have optimized performance when IP Camera over 8 channels.5. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.6. Please use different network section for LAN 1 and LAN 2.7. Both spot output support analog channel only.8. Please use SATA 6 to connect first HDD.9. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance.

Others

Ps The latest update should be listed on the top



Release Notes

Product	EH6216H+, EH6108H+
Version	X9.03.24.00.07j
Introduction	Official Release for H.S.I implementation
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Implement H.S.I module(High speed integration)2. Solve bugs about camera setting could not be saved3. Modify EPSON POS 0x00 issue4. Remove "TM" from AVer logo
Known Issues	<ol style="list-style-type: none">1. Please install HDD first before running and remote/ISP upgrading the system. User can only setup system setting if no HDD installed.2. The frame rate of 2nd video stream of remote site is limited to 15fps per analog channel.3. It would pop up a dialog to check compatibility with remote s/w installation in the first time in Windows 7 operating system.4. Connection with 8 channel IP camera would be the optimized performance of hybrid application. Please use Intelligent streaming to have optimized performance when IP Camera over 8 channels.5. Audio adjustment needs to be through speaker in remote download playback and real-time playback in Win7 operating system.6. Please use different network section for LAN 1 and LAN 2.7. Both spot output support analog channel only.8. Please use SATA 6 to connect first HDD.9. Video input with bad signal and noise is strongly suggested not to connect to avoid affecting recording performance.

Others

Ps The latest update should be listed on the top

