

Revision History:

Y/M/D	Author	DVR version	IP Cam Patch version
2015/05/22	Chris	7.9.0.0038	2.7.1011.13
2015/01/19	Chris	7.9.0.0037	2.7.108.10
2014/08/01	Chris	7.9.0.0036	2.5.105.8
2014/03/06	Karen	7.9.0.0035b	1.5.1014.3
2013/12/20	Karen	7.9.0.0035	1.5.1014.3
2013/09/06	Peter	7.9.0.0034b	1.1.100.2

Ps The latest update should be listed on the top



Release Notes

Product	IWH5416 series
Version	7.9.0.0038
Introduction	Official release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Upgrade IPCam patch to support AVer new IPCam: FB2026
Known Issues	<ol style="list-style-type: none">1. The C drive cannot be set to the recording path2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally.3. HDD format is not allowed in system setting while DVR is recording4. Support 80 mega pixels resolution for all IP camera channels connected to one system.5. Some Icon and UI will abnormal if main UI default setting is based on "Electric Red".6. Frame of IP cam will drop in preview mode while CPU loading is high.7. KVM switch is not supported.
Others	NA



Release Notes

Product	IWH5416 series
Version	7.9.0.0037
Introduction	Official release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Upgrade IPCam patch to support AVer new IPCam: FB1026, FC1000, FD2000, FB2026 series.2. Fixed CBE TCP POS link delay and data missing issue.3. Fixed hard disk detected failed issue.
Known Issues	<ol style="list-style-type: none">1. The C drive cannot be set to the recording path2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally.3. HDD format is not allowed in system setting while DVR is recording4. Support 80 mega pixels resolution for all IP camera channels connected to one system.5. Some Icon and UI will abnormal if main UI default setting is based on "Electric Red".6. Frame of IP cam will drop in preview mode while CPU loading is high.7. KVM switch is not supported.
Others	NA



Release Notes

Product	IWH5416 series
Version	7.9.0.0036
Introduction	Official release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Upgrade new IPCam patch2. Bug fixed:<ol style="list-style-type: none">(1) fixed remote control connection failed issue.(2) add recover function when user account file is corrupt.(3) fixed IWH series crash issue when connect to IPCam with new IPCam firmware(version 75).
Known Issues	<ol style="list-style-type: none">1. The C drive cannot be set to the recording path2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally.3. HDD format is not allowed in system setting while DVR is recording4. Support 80 mega pixels resolution for all IP camera channels connected to one system.5. Some Icon and UI will abnormal if main UI default setting is based on "Electric Red".6. Frame of IP cam will drop in preview mode while CPU loading is high.7. KVM switch is not supported.
Others	NA



Release Notes

Product	IWH5416 series
Version	v7.9.0.0035b
Introduction	Official release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Fix problem about the files cannot import to system when user no installed the hard disk.2. Fix the problem of abnormal motion detection operation.3. Fix problem about server name changes of setup wizard.4. Fix problem about the maximum connection of remote real time playback is up to 5.
Known Issues	<ol style="list-style-type: none">1. The C drive cannot be set to the recording path2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally.3. HDD format is not allowed in system setting while DVR is recording4. Support 80 mega pixels resolution for all IP camera channels connected to one system.5. Some Icon and UI will abnormal if main UI default setting is based on "Electric Red".6. Frame of IP cam will drop in preview mode while CPU loading is high.7. KVM switch is not supported.
Others	NA

Ps The latest update should be listed on the top



Release Notes

Product IWH5416 series

Version v7.9.0.0035

Introduction Official release

Hardware NA
Compatibility

Operating Systems NA

Compatibility List NA

Change Log

1. Support Korean Language
2. Support iSCSI detection mechanism
3. Fix problem about preview one split without image in TV OUT
4. Fix problem about IP CAM initial value error
5. Fix problem about compact mode text display position error
6. Fix problem about alarm record which pre-record time error
7. Fix problem about IP CAM connection lost mechanism
8. Fix problem about DVR not receive IP CAM audio voice
9. Fix problem about IP CAM no sound output in preview mode
10. Under camera setup mode keypad to appear
11. Add new IP CAM version

Known Issues

1. The C drive cannot be set to the recording path
2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally.
3. HDD format is not allowed in system setting while DVR is recording
4. Support 80 mega pixels resolution for all IP camera channels connected to one system.
5. Some Icon and UI will abnormal if main UI default setting is based on "Electric Red".
6. Frame of IP cam will drop in preview mode while CPU loading is high.
7. KVM switch is not supported.



Release Notes

Product IWH5416 series

Others NA

Ps The latest update should be listed on the top



Release Notes

Product	IWH5416 series
Version	v7.9.0.0034b
Introduction	Official release for H.S.I implementation
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Implement H.S.I module(High speed integration)2. Fix problem about alarm trigger which need to take 10 seconds3. Fix problem about recording error when alarm trigger4. Fix problem about POS error which cause system crash5. Fix problem about POS search error
Known Issues	<ol style="list-style-type: none">1. The C drive cannot be set to the recording path2. System would not save DVR setting if HDD is not installed in the system first and shutdown DVR abnormally.3. HDD format is not allowed in system setting while DVR is recording4. Support 80 mega pixels resolution for all IP camera channels connected to one system.5. Some Icon and UI will abnormal if main UI default setting is based on "<u>Electric Red</u>".6. Frame of IP cam will drop in preview mode while CPU loading is high.7. KVM switch is not supported.

Others

Ps The latest update should be listed on the top

