

Revision History:

Y/M/D	Author	FW version	NA version
2015/5/20	Chris	2.17.1078.89	N/A
2014/8/21	Kelly	2.15.1076.78	N/A
2014/7/17	Kelly	2.13.1073.76	N/A
2014/6/30	Kelly	2.13.1073.75	N/A
2014/5/29	Kelly	2.10.1071.73	N/A
2014/4/15	Kelly	2.9.1062.71	N/A

Ps The latest update should be listed on the top



Release Notes

Product	IP Cam Series
Version	2.17.1078.89
Introduction	Official Release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Increase 3A schedule configuration.2. Fix SD card storage bug.
Known Issues	<ol style="list-style-type: none">1. Recommended video player for recording file playback : Media Player Classic, BS Player(Android), Window Media Player, QuickTime, GOM Player.2. Frame rate will descend 6% while SD-Card accessing data.3. Quick Focus function may trigger Cross Detection alarm.4. Cross Detection is sensitive to image noise.5. Start patrol function under corridor mode will cause the frame rate to decrease.6. Turn on 3D de-noise and IVA functions at the same time will lead to the lower frame rate.
Others	NA



Release Notes

Product	IP Cam Series
Version	2.15.1076.78
Introduction	Official Release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Improve the capability of load-balancing.2. Fix the frame rate-dropping bug.
Known Issues	<ol style="list-style-type: none">1. Recommended video player for recording file playback : Media Player Classic, BS Player(Android), Window Media Player, QuickTime, GOM Player.2. Frame rate will descend 6% while SD-Card accessing data.3. Quick Focus function may trigger Cross Detection alarm.4. Cross Detection is sensitive to image noise.5. Start patrol function under corridor mode will cause the frame rate to decrease.6. Turn on 3D de-noise and IVA functions at the same time will lead to the lower frame rate.
Others	NA



Release Notes

Product	IP Cam Series
Version	2.13.1073.76
Introduction	Official Release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Fix model name display error of FB3028-RT1
Known Issues	<ol style="list-style-type: none">1. Recommended video player for recording file playback : Media Player Classic, BS Player(Android), Window Media Player, QuickTime, GOM Player.2. Frame rate will descend 6% while SD-Card accessing data.3. Quick Focus function may trigger Cross Detection alarm.4. Cross Detection is sensitive to image noise.5. Start patrol function under corridor mode will cause the frame rate to decrease.6. Turn on 3D de-noise and IVA functions at the same time will lead to the lower frame rate.
Others	NA



Release Notes

Product	IP Cam Series
Version	2.13.1073.75
Introduction	Official Release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Compatible with Milestone XProtect Series through ONVIF
Known Issues	<ol style="list-style-type: none">1. Recommended video player for recording file playback : Media Player Classic, BS Player(Android), Window Media Player, QuickTime, GOM Player.2. Frame rate will descend 6% while SD-Card accessing data.3. Quick Focus function may trigger Cross Detection alarm.4. Cross Detection is sensitive to image noise.5. Start patrol function under corridor mode will cause the frame rate to decrease.6. Turn on 3D de-noise and IVA functions at the same time will lead to the lower frame rate.
Others	NA

Ps The latest update should be listed on the top



Release Notes

Product	IP Cam Series
Version	2.10.1071.73
Introduction	Official Release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none">1. Fix FW Upgrade Issue.
Known Issues	<ol style="list-style-type: none">1. Recommended video player for recording file playback : Media Player Classic, BS Player(Android), Window Media Player, QuickTime, GOM Player.2. Frame rate will descend 6% while SD-Card accessing data.3. Quick Focus function may trigger Cross Detection alarm.4. Cross Detection is sensitive to image noise.5. Start patrol function under corridor mode will cause the frame rate to decrease.6. Turn on 3D de-noise and IVA functions at the same time will lead to the lower frame rate.
Others	NA

Ps The latest update should be listed on the top



Release Notes

Product	IP Cam Series
Version	2.9.1062.71
Introduction	Official Release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	NA
Known Issues	<ol style="list-style-type: none">1. Recommended video player for recording file playback : Media Player Classic, BS Player(Android), Window Media Player, QuickTime, GOM Player.2. Frame rate will descend 6% while SD-Card accessing data.3. Quick Focus function may trigger Cross Detection alarm.4. Cross Detection is sensitive to image noise.5. Start patrol function under corridor mode will cause the frame rate to decrease.6. Turn on 3D de-noise and IVA functions at the same time will lead to the lower frame rate.
Others	NA

Ps The latest update should be listed on the top

