

Revision History:

---

Y/M/D	Author	NVR version	IP Cam Patch version
2015/08/10	Vivian	2.3.1025.26	2.7.1026.28
2015/06/15	Chris	2.3.1024.25	2.7.1022.25
2015/05/22	Chris	2.3.1021.24	2.7.1022.21
2014/12/08	Chris	2.3.1020.21	2.7.1015.18
2014/08/22	Chris	2.3.1017.20	2.5.106.13
2014/02/26	Karen	1.5.100.9	1.7.103.4

Ps The latest update should be listed on the top



## Release Notes

---

	E1008
Version	2.3.1025.26
Introduction	Official release
Hardware Compatibility	E1008,E1008H
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none"><li>1. The PTZ preset increase to 256 point.</li><li>2. Upgrade IPCam patch, support AVer SD2026</li></ol>
Known Issues	<ol style="list-style-type: none"><li>1. Schedule backup to NAS will increase system loading obviously, it will effect system performance of another function.</li></ol>
Others	NA



## Release Notes

---

	E1008
Version	2.3.1024.25
Introduction	Official release
Hardware Compatibility	E1008,E1008H
Operating Systems	NA
Compatibility List	NA
Change Log	1. Fixed streaming display problem when only connected with VGA output device after upgraded firmware 2.3.1021.24.
Known Issues	2. Schedule backup to NAS will increase system loading obviously, it will effect system performance of another function.
Others	NA



## Release Notes

---

	E1008
Version	2.3.1021.24
Introduction	Official release
Hardware Compatibility	E1008,E1008H
Operating Systems	NA
Compatibility List	NA
Change Log	<ol style="list-style-type: none"> <li>1. Upgrade IPCam patch, support AVer FB2026.</li> <li>2. Increase new function:             <ol style="list-style-type: none"> <li>(1) Support NVR motion detection, it's good fit for 3<sup>rd</sup> party camera.</li> <li>(2) Increase IVA recording setting.</li> <li>(3) Increase hard disk failed alarm.</li> <li>(4) E-Map's icon support preview function.</li> <li>(5) Increase schedule backup to NAS.</li> <li>(6) Support POS key word alarm setting.</li> <li>(7) Support ACS setting (only for Russia customer).</li> <li>(8) Add recording authority in control right setting.</li> <li>(9) Increase POS erase setting.</li> </ol> </li> <li>3. Improvement:             <ol style="list-style-type: none"> <li>(1) real-time to sync record streaming when dragging the time scroll bar in playback mode.</li> <li>(2) Only display AVer protocol when searched AVer homemade camera.</li> <li>(3) Revised Epson POS protocol integration.</li> <li>(4) User can select which streaming they want when connect to ED5000(AVer fisheye camera) in camera setting.</li> </ol> </li> </ol>
Known Issues	<ol style="list-style-type: none"> <li>1. Schedule backup to NAS will increase system loading obviously, it will effect system performance of another function.</li> </ol>
Others	NA

Ps The latest update should be listed on the top



## Release Notes

---

	E1008
Version	2.3.1020.21
Introduction	Official release
Hardware Compatibility	E1008,E1008H
Operating Systems	NA
Compatibility List	NA
Change Log	1. Upgrade IPCam patch, support AVer FB1026, FC1000, FC1000-1, FD2000-1, FD2000-2, FD2000-3
Known Issues	NA
Others	NA

Ps The latest update should be listed on the top



## Release Notes

---

### E1008

Version 2.3.1017.20

Introduction Official release

Hardware E1008,E1008H  
Compatibility

Operating Systems NA

Compatibility List NA

Change Log

1. Support IVA setting (only for AVer IP camera).
2. Support Optimized recording function (only for AVer IP camera).
3. Increase reset to default button.
4. Support MPEG4 format when using clip video function.
5. Support POS function with network protocol.
6. Revised the language package.
7. New Font.
8. Support PCViewer:
  - (1)Support IE9+, Firefox 26+, Chrome31+
  - (2)Support 2-way audio with NVR.
  - (3)Display internet bandwidth and average FPS.
9. Upgrade IP Cam patch to support AVer new IP camera FD1020, FC1020-P, FC2020-P1.
10. Modify playback for fast forward & backward to display multiple i-frames.

Known Issues

1. Can't disable "overwrite" function in this version.
2. PCViewer doesn't support auto re-connection and might cause browser crash when disconnected.
3. User can't change the time setting of IP camera's IR-Cut filter when switch the to schedule type.
4. Not support Camera settings for "Corridor" video stream mode Camera.



## Release Notes

---

E1008

Others

NA

Ps The latest update should be listed on the top



## Release Notes

---

### E1008

Version	1.5.100.9
Introduction	Official release
Hardware Compatibility	NA
Operating Systems	NA
Compatibility List	NA
Change Log	NA
Known Issues	<ol style="list-style-type: none"><li>1. Not support Camera settings for “Corridor” video stream mode Camera.</li><li>2. Maximum support bitrate of IP CAM audio G.726 is 16kbps.</li><li>3. Restrict E-map authorization of user level account may cause the system crash.</li></ol>
Others	NA

Ps The latest update should be listed on the top

