



Products: PTZApp for Windows

Software Version: 1.3.1074.75

Published Date: November 23^h, 2018

Copyright © 2016

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement.....	2
Important Notice	3
New Features	4
Problems Fixed	6
Known Issues	7



Revision History and System Requirement

Software Version	Region	OS	Date	Model
1.3.1074.75	WW	Windows	November 23,2018	Aver Conference Camera
1.3.1073.74	WW	Windows	October 12,2018	Aver Conference Camera
1.3.1071.73	WW	Windows	September 05, 2018	Aver Conference Camera
1.3.1060.64	WW	Windows	May 5, 2018	Aver Conference Camera
1.3.1054.60	WW	Windows	March 16, 2018	AVer Conference Camera
1.3.1050.54	WW	Windows	November 17, 2017	AVer Conference Camera
1.2.1046.50	WW	Windows	July 26, 2017	AVer Conference Camera
1.2.1034.46	WW	Windows	June 19,2017	AVer Conference Camera
1.2.1034.45	WW	Windows	May 26, 2017	AVer Conference Camera
1.2.1030.32	WW	Windows	August 5, 2016	AVer Conference Camera
1.2.1023.28	WW	Windows	April 8, 2016	AVer Conference Camera
1.0.1021.23	WW	Windows	January 11, 2016	AVer Conference Camera
1.0.1015.21	WW	Windows	November 10, 2015	AVer Conference Camera
1.0.1010.15	WW	Windows	September 2, 2015	AVer Conference Camera
1.3.1071.73	WW	Windows	September 04, 2018	AVer Conference Camera



Important Notice

1. PTZApp is a free software and controlling the PTZ Camera, adjusting the camera's image quality, diagnosing operating status, and viewing live video form the camera.
2. PTZApp assists with firmware upgrades
3. Support Operating System
 - Windows 7: 32-bit and 64 –bit
 - Windows 8 and 8.1 Standard, Pro, and Enterprise: 32-bit and 64 bit
 - Windows 10



New Features

Software Version	New Features
1.3.1074.75	<ol style="list-style-type: none"> 1. Add “ auto power on/off” option for VB342. 2. Add Enable/disable device buttons option for VB342 3. Add displaylink enable/disable option for VB342 (While connecting to Chrome box, please select “OFF”) <p>*To have these new options, please upgrade VB342 FW with version: 0.0.4002.48</p> <p><u>System</u></p> <p>Auto power on <input type="text" value="On"/></p> <p>Enable device buttons <input type="text" value="On"/></p> <p>Displaylink <input type="text" value="On"/></p>
1.3.1071.74	Support flip image setting for CAM540/CAM340/VC322
1.3.1071.73	<ol style="list-style-type: none"> 1. Support CAM540 2. Add DisplayLink driver 3. Add “3.5mm “ description in front of External MIC only & mix in (Phone in jack function). 4. Keep PTZapp always on the top of the PC screen in Windows OS.
1.3.1060.64	<ol style="list-style-type: none"> 1. Support Skype for Business –Far end Camera Control. 2. Add VB342 in support list
1.3.1054.60	None
1.3.1050.54	Add VC322 in support list
1.2.1046.50	<ol style="list-style-type: none"> 1. Support FONE520 AutoTune 2. Add audioDump for VC520. 3. Support VC520+ 4. Add Transfer mode for CAM340
1.2.1034.46	None
1.2.1034.45	1. Support FONE520 & CAM340
1.2.1030.32	<ol style="list-style-type: none"> 1. Support AEC/NR enable/disable selection. 2. Add Home position selection. 3. Add Suspend position selection. <p>*Firmware must be upgraded to v0.0.0016.06 for VC520/CAM520 & v.0.0.1002.04 for CAM530.</p>
1.2.1023.28	<ol style="list-style-type: none"> 1. Adds remote control selection – User may select the type of remote control used. 2. Supports Hotkey function.



	<ol style="list-style-type: none">3. Supports camera select function on remote control.4. Adds "auto" function selection for backlight compensation.5. Adds continuous auto focus function selection.
1.0.1021.23	<ol style="list-style-type: none">1. Supports CAM530.
1.0.1015.21	<ol style="list-style-type: none">1. Adds troubleshooting function.2. Adds Skype Plug in multi support – When you install AVer PTZApp software, you can select options.3. Adds auto displaying better resolution PTZApp when monitor is smaller than 14' with resolution greater than 1920.
1.0.1010.15	<ol style="list-style-type: none">1. The 1st release.



Problems Fixed

Software Version	Problem Fixed
1.3.1074.75	None
1.3.1071.74	None
1.3.1071.73	None
1.3.1060.64	None
1.3.1054.60	<p>1. When users who use specific Win7 execute Recovery Tool with CAM340, it pop-up a window "The device is not cam340." (RecoveryTool_1.0.100.11)</p> <p>2. When users who use specific Win7 execute Recovery Tool with VC322, the power adapter is un-plug and re-plug during phase II, it still shows " Please connect to VC322." (RecoveryTool_1.0.100.11)</p> <p>Function and Feature add/modification</p> <p>Check HID is working, before ISP. If HID doesn't work, it will show " update failed warning after ISP. (It occurs on specific PC and use some video software and PTZApp ISP at the same time.)</p>
1.3.1050.54	None
1.2.1046.50	None
1.2.1034.46	Fix FONE520 unable boot issue
1.2.1034.45	None
1.2.1030.32	None
1.2.1023.28	None
1.0.1021.23	None
1.0.1015.21	None
1.0.1010.15	None



Known Issues

Software Version	Known Issues
1.3.1074.75	None
1.3.1071.74	None
1.3.1071.73	None
1.3.1060.64	None
1.3.1054.60	None
1.3.1050.54	None
1.2.1046.50	None
1.2.1034.46	None
1.2.1034.45	None
1.2.1030.32	None
1.2.1023.28	None
1.0.1021.23	None
1.0.1015.21	None
1.0.1010.15	None

