



**Products:** CAM340+

**Firmware Version:** 0.0.1000.46

**Published Date:** OCT.07, 2021

**Copyright © 2016**

---

## Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

## Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

## Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

## Content

Revision History and System Requirement .....	2
Important Notice .....	3
New Features .....	4
Problems Fixed .....	5
Known Issues .....	6





## **Important Notice**

1. During system upgrade, please DON'T turn off the power for any reasons.
2. Please upgrade to PTZApp2: v. 2.0.1013.15 (MAC); v. 2.0.1016.19 (Windows) to get full functions and better using experience.





## Problems Fixed

Firmware Version	Problem Fixed
0.0.1000.46	Fix bugs: Barco X30/X50 compatible issue Fix bugs: When starting VC meeting, the camera will be zoomed out to wide.
0.0.1000.40	Fix bugs: In Win10 20H, digital PAN and TILT malfunctions in AMCAP tool. In Chrome box, the camera shows black screen while starting Google Meet meetings for few seconds.
0.0.1000.38	None
0.0.1000.36	Fix bug of UVC control: Opposite Tilt value
0.0.1000.34	None
0.0.1000.22	None
0.0.1000.18	None



## Known Issues

Firmware Version	Problem Fixed
0.0.1000.46	None
0.0.1000.40	None
0.0.1000.38	None
0.0.1000.36	None
0.0.1000.34	None
0.0.1000.22	None
0.0.1000.18	None

