

Firmware Release Note

Release date	2013/12/30
FW version	AVer_V1.0.40
Brand	AVer
Model	FC2020-P (1.3M Cube type, wired model with PoE) FC2020-PW (1.3M Cube type, wireless model without PoE) FV1306 (1.3M mini vandal dome) FV2006 (2.0M mini vandal dome)
Integration with AVer NVR	IPCam Patch _1.5.1014.3
Notes	
Bugs fixed	
1	Issue: Under IE10, if users enable Samba function (DI/DO >> Input Setting >> Input Action >> Samba) and press "apply" button, the check mark will disappear. Solution: This new FW can fix this bug and the Samba function can work properly.