



**Products:** CAM530

**Firmware Version:** 0.0.1002.50

**Published Date:** September 09, 2019

**Copyright © 2016**

---

## Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

## Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

## Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

## Content

Revision History and System Requirement .....	2
Important Notice .....	3
New Features .....	4
Problems Fixed .....	5
Known Issues .....	6



## Revision History and System Requirement

Firmware Version	Region	Date
0.0.1002.50	WW	September 09, 2019
0.0.1002.46	WW	October 11,2018
0.0.1002.36	WW	April 20,2018
0.0.1002.16	WW	December 2, 2016
0.0.1002.04	WW	August 5, 2016
0.0.1000.26	WW	April 15, 2016
0.0.1000.12	WW	February 2, 2016
	WW	
	WW	
	WW	
	WW	
	WW	



## **Important Notice**

1. PTZApp must be upgraded to v1.0.1021.23 in order to upgrade firmware.
2. PTZApp must be upgraded to v1.2.1023.28 in order to select the type of remote control used.



## New Features

Firmware Version	New Features
0.0.1002.50	Add ZOOM ROOM XU control (preset function)
0.0.1002.46	None
0.0.1002.36	Add VISCA_POWER ON/OFF (display / suspend pos.)
0.0.1002.16	1. Support 18x zoom 2. Add sleep mode
0.0.1002.04	1. Support AEC/NR enable/disable selection via PTZApp 2. Add home position selection via PZApp 3. Add suspend position selection via PTZAp *PTZApp must be upgraded to v1.2.1030.32
0.0.1000.26	1. Add remote control selection –user may select the type of remote control used. 2. Support FaceLumi funcion
0.0.1000.12	First release

\*FaceLumi: Enhance facial features by correcting skin tone and activates auto focus and auto exposure.



## Problems Fixed

Firmware Version	Problem Fixed
0.0.1002.50	None
0.0.1002.46	Fix Remote control IR failure issue. This issue happens when turning on camera without connecting HDMI or USB cable.
0.0.1002.36	None
0.0.1002.16	None
0.0.1002.04	None
0.0.1000.26	None
0.0.1000.12	None



## Known Issues

Firmware Version	Problem Fixed
0.0.1002.50	None
0.0.1002.46	None
0.0.1002.36	None
0.0.1002.16	None
0.0.1002.04	None
0.0.1000.26	None
0.0.1000.12	None

