



Software Version: 2.17.1028.31

Published Date: April 15th, 2017

Copyright © 2016

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL AVER BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE AVER PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF AVER IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, AVER WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. AVER WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT AVER RECEIVED FROM THE END-USER FOR THE PRODUCT.

Content

Revision History and System Requirement	2
Important Notice	3
Upgrade Instructions	4
New Features	5
Problems Fixed	6
Known Issues	7

Revision History and System Requirement

Software Version	Region	Date	Model
2.17.1028.31	WW	Aprial 15, 2017	EZmeetup Mac
2.15.1022.25	WW	Oct 17, 2016	EZmeetup Mac
2.13.1018.22	WW	July 12, 2016	EZMeetup Mac
2.11.1015.18	WW	Dec 29th,2015	EZMeetup Mac
2.9.1011.15	WW	Jul 13th,2015	EZMeetup Mac
2.7.107.11	WW	April 14th, 2015	EZMeetup Mac

Important Notice

1. EZMeetup is a mobile and collaborative software/app designed only for AVer EVC300 and EVC900 video conferencing system.
2. EVC900 and EVC300 can accommodate up to 9 EZMeetup users communicating each other simultaneously.
3. To receive videos on EZMeetup, please enable H.264 and H.263+ video codecs on EVC300 and EVC900 video conferencing system.
4. Minimum Hardware Requirements (720P video resolution)
 - Intel Core 2 Duo 2.4GHz or higher
 - 2GB DDR2 SDRAM
5. Recommended Hardware Requirement
 - Intel Core i5 Duo 2.4 GHz or higher
 - 8GB DDR3 SDRAM
6. Supporting Operating System
 - OSX 10.9.1
 - OSX 10.10.1
 - OSX 10.10.2
7. Video Resolution
 - Live Video
 - Transmit and Receive resolution up to Full HD 1080p 30 fps
 - Content Sharing
 - Transmit resolution up to 720p 10 fps
 - Receive resolution up to 720p 30 fps

it totally depends on your available bandwidth and camera resolutions

Bandwidth requirement table

Bandwidth	Transmit Resolution	Receive Resolution
2048Kbps	1080p	1080p
1536Kbps	720p	720p
1024Kbps	720p	720p
768Kbps	480p	480p
512Kbps	480p	480p
384kbps	480p	CIF
256kbps	CIF	CIF
128kbps	QCIF	QCIF

Install Instructions


1. Download from AVer website

<http://communication.aver.com/DownloadFile.aspx?n=2835|B2A9C3ED-AF08-4AA6-B9B0-85D15F0EE266&t=ServiceDownload>

2. Find the downloaded file – usually it is saved on your Desktop or in the Downloads folder.



3. Double click the dmg file to mount it. A new Finder window will pop out showing its contents:
 - If the Find window also contains a shortcut icon to “Applications”, drag and drop the app onto the shortcut
 - If it is not the case, please double-click the mounted volume on your desktop and drag the app icon to the “Application” icon in the Finder sidebar.



New Features

Software Version	New Features
2.17.1028.31	<ol style="list-style-type: none"> 1. [UI] Add far end controller option 2. [UI] Add far end mute notification 3. [UI] Add enable H.264 HP option
2.15.1022.25	<ol style="list-style-type: none"> 1. [Application] Support Asterisk. 2. [UI] Allow to define system name in general setting.
2.13.1018.22	<ol style="list-style-type: none"> 1. [Application] Content Sharing: User may choose the desired application for content sharing. 2. [UI] Incoming Call: Displays graphic user interface.
2.11.1015.18	<ol style="list-style-type: none"> 1. [System] Support Full HD (1080p) resolution 2. [Application] Capture and Recording: users can capture and record meetings 3. [UI] Content Sharing Info: Add information including transmit and receive contenting sharing 4. [UI] Troubling shooting : Go to Settings / Feedback , When a problem occurs, you can save log to your storage.
2.9.1011.15	<ol style="list-style-type: none"> 1. [System] Change trial period from 5 minutes to 30-days 2. [System] Support Acoustic Echo Cancelling (AEC) 3. [UI] More Connection Info: add information including Live and Presentation Packet Loss 、 Jitter 、 Video Frame Rate. 4. [UI] SIP Server ID: Go to SIP Account, and enter Account name 、 Register Server 、 Proxy Server. SIP Server ID will appear automatically 5. [Applications] BFCP Content Sharing: users can share the presentation slides easily 6. [Protocol] SRTP: through SRTP, RTP payloads will be encrypted to prevent sniffer, and hence secure communication between users.
2.7.107.11	<ol style="list-style-type: none"> 1. [Protocol] SIP TLS: through TLS, SIP payloads will be encrypted to prevent malicious or unwanted modifications. One good side-effect is that NAT-traversal can be achieved by TLS connections since SIP payloads will not be altered by NAT-enabled routers. 2. [Application] EZMeetup MAC can receive contents from/ to the EVC300/EVC900 video conferencing systems.

Problems Fixed

Software Version	Problem Fixed
2.17.1028.31	None
2.15.1022.25	None
2.13.1018.22	None
2.11.1015.18	1. [UI] Modify Content sharing icon 2.[System] Improve Acoustic Echo Cancelling (AEC)
2.9.1011.15	None
2.7.107.11	None

Known Issues

Firmware Version	Known Issues
2.17.1028.31	EZMeetup will occur display error when user has been executed PTZ application with USB Cam before execute EZMeetup MAC
2.15.1022.25	EZMeetup will occur display error when user has been executed PTZ application with USB Cam before execute EZMeetup MAC
2.13.1018.22	EZMeetup will occur display error when user has been executed PTZ application with USB Cam before execute EZMeetup MAC.
2.11.1015.18	EZMeetup will occur display error when user has been executed PTZ application with USB Cam before execute EZMeetup MAC.
2.9.1011.15	EZMeetup will occur display error when user has been executed PTZ application with USB Cam before execute EZMeetup MAC.
2.7.107.11	None